

JOINT INSPECTION NOTE

Today on 02/12/2021 we the following officers jointly inspected the survey line of road Choura Gali to Ladote via Muku Brade passing through Co. 73/R, 74/R and 76/R of kandi Range, Rajouri Forest Division and found this is the only survey line where minimum Forest land and Forest Crop is involved and there is no other alternative than this survey line for connectivity of this village

Total length of road	RD	Total length passing through forest	Width to be required	Remarks
15.00	RD1 0/C-1/600 RD2 5/100-5/775 RD3 13/0-13/200	1600 675 200	6Mtr	Alignment of road is same as per joint inspection already done.

Detail of area involved is as under:-

Width of the road 6 Mtr

Area under road construction = 1.485 Ha

Dumping sites identified in the forest area:-

S.No	Size of Dumping sites	Area
1	30x25	750 M ²
2	30x25	750 M ²
3	30x25	750 M ²
4	30x25	750 M ²
	Total	3000 M ²

Total area under Dumping Sites=0.3

Total area under road alignment and dumping sites = 1.485 + 0.3 = 1.785 Ha

Block Officer
(Kashmir)
Block Officer
Kashmir
JE
PWD(R&B)Division
Rajouri

P.D.
B. Gujral
(Kashmir)
AEE
PWD(R&B)Division
Rajouri

Divisional Forest Officer
Rajouri Forest Division
Rajouri
Range Officer
Kandi
Executive Engineer
PWD (R&B) Division
Rajouri