## SITE INSPECTION REPORT.

1	Name of the Project:	Construction of 132/33 KV Transmission Line from Grid Sub-station Boudh to proposed 220/132/33 KV Grid Substation at Kiakata.						
2	Name of the District:	Angul						
	Name of the Division:	Athmallik						
3	Date of inspection	20.03.2023 & 26.05.2023						
1	Name & Designation of the inspecting Officer	Sri Santosh Kumar Koppula, I.F.S., Divisional Forest Officer, Athmallik Division						
;	Name and designation of other officer	Forest Depar	AND THE RESIDENCE OF THE PARTY					
	who attended the inspection including the User Agency.	1. Sri Santosh Kumar Koppula, I.F.S.(DFO) 2.Sri Santosh Bhoi (RO, Madhapur) 3.Sri Dipti Ranjan Biswal, Forester		OFO) oi (RO,	1.Sri K.C. Pattnaik, D.G.M. 2.Sri B.K. Naik, S.D.O., Kiakata, OPTCL. 3.Sri Chitrasen Behera 4. Sri P.C. Kisku, Asst. Engineer. 5. Sri Ajit Ku. Nayak, Manager, CEMC, BBSR.			
6	Legal Status of Forest land proposed	Tahasil			Stat	us of For	est la	nd
	for diversion	Athmallik		Reserve For	rest		OSEADV.	venue Forest
				1 0 11				4.837 Ha.
7	If the area required for diversion has been demarcated on the ground.	Ground area concrete pil		posed for di	vers	ion was c	leman	cated with
8	Item wise break-up of the Forest land proposed for diversion.	×	Forest ar		ea in Non- forest area in Ha. Total area		Total area in Ha.	
		For Transmissi Line	ion	4.837 Ha.		35.368	Ha.	40.205 Ha.
		Total	35)	4.837 Ha.		35.368	Ha.	40.205 Ha.
9	Condition of vegetation and type of forest in applied area	Open Forest & Scrub.						
10	Position of wildlife in general.	Presence of Jungle foul, fox, elephant etc. is noticed along the tract.						
11	Whether the applied area is involved with any Eco-sensitive Zone / National Park / Sanctuary.	No						
12	No of trees to be felled and its impact on the Eco-system.	279 No. of trees are available over 4.837 Ha. of Revenue Forest land area. No adverse impact on the ecosystem is foreseen.						
13	Details of broken up area and reclamation done if any. (Mining cases)	Nil						
14	Position of displacement of people and adequacy of rehabilitation if any.	No displacement of people is necessary for this project.						
15	Position of rare and endangered species available & importance of area from Eco-social point of view.	Not available in that area.						
16	Non-forest land used in the project and non-forest land selected for Compensatory Afforestation is included in the DLC Report or not.	i. Non-forest land used in the project is not included in the DLC report.     ii. No Non-forest land is selected for Compensatory Afforestation.						

17	Suitability of the identified non-forest land / Degraded forest area for Compensatory Afforestation.	Diversion pro					
18	Violation of Forest conservation Act- 1980, if any and action taken there- on.	Violation of FC Act, 1980 noticed during site inspection are as follows:- Various Angle Points and Suspension Points have been constructed in forest patches without Stage-I approval. GPS coordinates of same points are mentioned below.					
		SI No	Easting	Northing			
		1	84.364395	20.864713			
		2	84.364055	20.864218			
		3	84.364055 84.363283	20.864218 20.864485			
				TOTAL PROPERTY AND ADDRESS OF THE PARTY.			
		3	84.363283	20.864485			
		3 4	84.363283 84.360642	20.864485 20.864680			

Divisional Forest Officer, Athmallik Division.

Athmallik Division