


SITE INSPECTION REPORT

Certified that, the undersigned has inspected the site on 12-08-2020 and site inspection report is as under.

The proposed area 0.789 Ha. is located in Anagodu Sec-4 area of Anagodu village Sy.No. 130, 131, 132 of Davnagere Taluk. This area is inevitable for user agency for Bharamasagara LIS Construction of raising main pipeline [CH-36.225 to 37.55 KM] for drinking water purpose. There is not much vegetation in the area. The area is partially open blank with shrubs and the proposed work will not cause much disturbances to the Flora and Fauna in the proposed area.

Date : 12-08-2020
Place : Davanagere


Deputy Conservator of Forests,
Davanagere Division, Davanagere