

- 37 -

Site inspection report of the District Forest Officer, Vikarabad for formation of road to Crystal Minerals situated at Sy.No.818 Doulthabad, Vikarabad District in Forest Compartment No.308 block Beat Doulthabad,in the Doulthabad RF of Vikarabad District.

On 15.02.2022 proceeded to Doulthabad RF block compartment no. 308, and observed that, formation of road to Crystal Minerals along the boundary of Doulthabad Forest Block. As the formation of road to Crystal Minerals situated at Sy.No.818 Doulthabad, Vikarabad District in Forest Compartment No.308 block Beat Doulthabad no damage is being caused to the Forest and there are no rare and endangered Forest flora and fauna in the proposed area. There are no protected archaeological / heritage site /defence establishment in the area proposed for formation of road to Crystal Minerals situated at Sy.No.818 Doulthabad, Vikarabad District.

Date: 22/04/2022


District Forest Officer
Vikarabad