




SITE INSPECTION REPORT

District Forest Officer, Cuddalore, inspected the proposed area in Thiruthuraiyur Reserve Forest of Cuddalore Forest Division on 21th July 2021 along with Cuddalore range field staff and Executive Engineer from TWAD Board department. The proposed Thiruthuraiyur RF area is having degraded forest. The proposed for drinking water Pipe line. TWAD Board department officials explained that the activities proposed for necessary for drinking water purpose. Right of Way is also admitted as per the Thiruthuraiyur RF notification. No tree felling is required for the project.


District Forest Officer,
Cuddalore Forest Division,
Cuddalore.


22.07.21

22/07/21