SITE INSPECTION REPORT

This is to certify that I have inspected the 1.33 hectare proposed forest area for

establishing 1x10 MVA 110/11KV sub station at Fsy no 54a of Kangod village (kansur)

Siddpur talluk Uttar kannada dist on 11-04-2019 along with Range Forest Officer, Sirsi

and found that the 1.33 hectare area is a forest sy.no.54a and it is acacia plantation

patch which was raised during the year 2006 to prevent encroachment by surrounding

villages. The proposed area for user agency is having acacia tree 270 in numbers, Acacia,

mangium 29 in number and other natural trees like Syzigium cumini (Neral),

Alseodaphne semicarpifolia (Mase), Careya arborea (Kavalu), Stichnus nux vomica

(Kasaraka), Terminalia elliptica (Matti), Lagerstroemia lanceolata (Nandi), Mangifera

indica (Mavu), Pterocarpus marsupium (Honne), Ficus recemosa (Basari) and others.

The proposed area is surrounded by Kangod, Kansur Fsy,no 54 on North, Betta sy.no.36 on South, Kangod, Kansur Fsy,no 54 on East and Kangod, Kansur Fsy,no 54 on

west.

The proposed area used for specific purpose and well intended to have components like approach road to sub station (0.0195 ha), 100m x 100m sub station

(1.00 ha) and line corridor of 145 m x 22m (0.32 ha).

The proposed area for 110/11kv sub station does not affect any declared or notified

monuments of historical, religious, archeological or recreation importance including wild life

sanctuary or national park.

Place: Sirsi

Date: 11-04-2019

Deputy Conservator of Forests,
Sirsi Division, Sirsi.

Z:\DCF Documents\2019-20\A3 LAND\Fc\Site Inspection Report...Doc