


JOINT INSPECTION CERTIFICATE


In inspection for the forest land comprising of Khata No.343, Khasra No.1326/424, Khatauni No.477/450 of forest land measuring 0-01-50 Hect. in Mohal Rakkar, Mauza Sidhbari, Tehsil Dharamshala, District Kangra (HP) held on 16.05.2014 by the following officers.

1. Sub-Divisional Magistrate, Dharamshala.
2. Divisional Forest Officer, Dharamshala.
3. Executive Engineer, I&PH Division, Dharamshala.

Alternative site was examined during the inspection. The forest land involved in the finally accept alignment is minimum and unavoidable because there is ~~no~~ Govt. Non-forest land which could be used for this purpose there is no objection is the Forest land coming alignment is diverted to I&PH Department Dharamshala for the construction of Water Tank in Mohal Rakkar, Mauza Sidhbari, Tehsil Dharamshala, District Kangra (HP).


Sub-Divisional Magistrate,
Dharamshala.


Executive Engineer,
I&PH Division, Dharamshala.


Divisional Forest Officer,
Dharamshala.