

JOINT INSPECTION REPORT FOR DUMPING YARD FOR THE WORK UP-GRADATION WIDENING AND IMPROVEMENT OF BUDANG CHUMBONG CHAKUNG SORENG ROAD UNDER ISC 100 % CSS.

Joint inspection is carried out on 17/01/2017, comprising the officials of MINES, MINERALS AND GEOLOGY DEPARTMENT GOVT OF SIKKIM and ROADS AND BRIDGES DEPTT. GOVT OF SIKKIM Soreng Division.

The following areas were inspected:-

Muck Dumping :

1	Soreng R.F 1.=Area 0.30 ha	P1 N 27*10'25.0" E 88*12'06.01"
2	Soreng RF 2.=Area 0.30 ha	P1 N 27*10'27.4" E 88*12'13.6"
3	Soreng RF 3.=Area 0.4 ha	P1 N 27*10'19.1" E 88*12'40.9"

Roads & Bridges Deptt.

1

Divisional Engineer II
Roads & Bridges Deptt
Govt. of Sikkim, Soreng

2

Assistant Engineer
Roads & Bridges Deptt.
Soreng, Sub-Division

3

JUNIOR ENGINEER
Road & Bridges Deptt.
Govt. of Sikkim,
Soreng (West)

Mines Minerals And Geology Deptt

1

Director
DIRECTOR

2

G. S. Lophche
Jk Din

3

Passang
17/01/17 Asst. Geologist

4. Tinku Shum Asst Geologist