




JOINT-INSPECTION-REPORT

Joint -Inspection Report of proposed Construction of link road Dhumi to Kharechi Km.0/000 to 10/165 comprising forest land, Mauja Dummi, Pawabo Jolo Shida Kurd Shida Kalan Sunog Tehsil Shimla (Rural) Distt, Shimla H.P. In this context the nodal office (F.C.A.) H.P. forest Deptt has raised observation with respect to joint inspection conducted on dated 11.10.2013. In the said joint inspection 603 trees and 362 sapling were mentioned in the proposed alignment Km.0/000 to 10/165, but in the enumeration list enclosed in the proposal 1147 nos trees (511Nos sapling and 636 trees) are involved.


To ascertain the ~~effect~~ the committee inspected the above alignment on 30.03.2017 and found that 1147Nos of trees (511Nos sapling and 636 trees) are coming in the proposed alignment and cannot be avoided and recommend there removal .


Assistant Engineer
Shimla Sub Division No.1
HP PWD Shimla-3.


Executive Engineer
Shimla Division No. I,
HPPWD Shimla-3


Range Forest Officer
Tara Devi Forest Range.
Shimla.


Divisional Forest Officer
Shimla Forest Division, Shimla-2


Sub Divisional Magistrate
Shimla Rural, Shimla-1
Shimla (Rural) H.P.