


JOINT INSPECTION REPORT


The Joint Inspection for the transfer of Govt. land in the name of Police Department for the construction of Police Post Building Jutogh at Mohal Totu Tehsil & Distt. Shimla has been carried out by the undersigned officers on 20.01.2017 vide Sub-Divisional Officer (C), Shimla Rural office letter No. SDS-(SDK) Jt. Insp./2017/43 dated 04.01.2017.


S.N	Kh.No.	Mohal	Kind of land as per revenue record	Area in Hect.	Remarks
1	1/3	Totu	Charagah Darakhtan	00-07-00	The said land has been rejected as there are number of trees i.e. Deodar and Kail were found and also HT electricity line passing over the site.
2	1/2/1	Totu	-do-	0-20-99	The said land is suitable for the construction of Police Post building as there is no water resource place, common path, cremation ground etc.


Asstt. Engineer,
Jutogh, Sub Div.
HPPWD Jutogh.



Range Forest Officer,
Taradevi Range, Totu


Tehsildar Rural
District Shimla.


Municipal Corp.
District Shimla


Asstt. Supdt. of Police
Shimla District, Shimla


SDM (R)
Shimla District, Shimla


Divisional Officer
Shimla District
Shimla