

## Joint Inspection report

Joint inspection of site proposed for construction of Leaf Analysis Laboratory and office Building at Dabbhi, Thanedhar of forest land in Mauza Lauga Khasra no. 574/1 and Agriculture land in Khasra No. 575 was conducted on 25.07.2013 and it was found that there is no alternative land available for the office building and Leaf analysis laboratory.

S. No.	Khasra No. of Forest land	Kind of land as per revenue record	Area required in ha.	Classification as per Forest record	No. of trees/saplings
1	575	Office building	0-01-24	Agriculture	-
2	574/1	Charagah	0-10-31	UPF	-

Dated:

Place:

Sub Divisional Magistrate  
Rampur

Tehsildar  
Karnahsain  
Distt. Shimla

Divisional Forest Officer  
Kotgarh  
Kotgarh Forest Division  
Kotgarh (H.P.)

Subject Matter Specialist (Hort)  
Subject Matter Specialist Horticulture  
Development Block (Tillog & Chopal)

Deputy Director Horticulture  
District Shimla, Shimla-2  
Deputy Director Horticulture  
Distt. Shimla-2 (H.P.)

*True & Attested*

Bee Keeping Development Officer  
Navbahar, Shimla-2