JOINT INSPECTION REPORT

Serial No.	Particular	Detail
1	Name of project	RCR from Bakchng to Thangshing
2	A brief of project	The name of the project is "Rural connectivity road (RCR) from Bakchung to Thangshing". This will be a very important road and will be the life line of people residing this area. This road is 1.43 Kilometer long and connects internal villages i. e. Bakchung, Thangshing, Tokal & Bermiok and to Singtam East Sikkim. The entire village depends upon agricultural production to run their livelyhood. There is no road connectivity for these villages and hence the Government has decided to upgrade the locality by providing/constructing a rural connectivity road funded by PMGSY and has been sanctioned by the concern Ministrey.
3	Date of inspection	15/12/2016 & 16/12/2016
4	Participants Participants	1)Bisnu Prasad Sharma, Assistant Engineer
	a) Name	2) Chopel Bhutia, Junior Engineer
	b) Designation 0	3)G. B. Pant, Block Officer
	0,	4) Govind Sharma, Revenue Surveyor
	a) Department	5) Karisma Rai, Forest Guard
5	c) Department Details of land in hacters	3) Karisina Kai, Forest Guard
	a) Private land b) Forest land c) Road reserve d) Total Land involve	a) 0.8360 ha b) 0.4416 ha c) Nil d) 1.2776 ha
6	Legal status of Forest Land	
	a) Gaucharan	a) Gaucharan = Nil
	b) Khasmal	c) Khasmal: 0.4416 ha
	c) Reserve forest	c) Reserve forest: Nil
	d) Road reserve	d) Road reserve: Nil
7		Plot Numbers for private land along the road = 27. 29. 10, 10/243, 243/810, 30, 60, 59, 57, 66, 65, 63, 62, 61, 61/284, 73, 74, 77, 75 257, 67, 60, & 18 (cadastral
8	Item wise break up of forest land required as per project.	Gaucharan = 0.00 Ha Khasmal = 0.4416 Ha Reserve forest = 0.00 Ha
9	Whether any national park / wildlife sanctury involved or not.	- NA -
10	Types of vegetation:	Open forest area with small poles bushes
11	Category of density:	Open
12	Number of trees / poles and forest produce involve or not, if yes	Trees = Nil
13	Indicate the detail of the plot. Topography of the project area, soil type of forest area.	Mild slope with Black cotton soil.

14	Brief observation of the	only 11 nos. of poles are to be removed from the road alignment without
	inspection team.	distrubing natural forest.
15	Sketch map of the proposed	
	project area showing the detail	Enclosed
	and alignment.	
16	Enumeration list of the trees.	Enclosed
17	Any other noteworthy	NA
	observations	- NA -
18	Certificate of DFO (T) concerned	
		Enclosed
	if tree felling is not involved .	

Sudip Tamang Junior Engineer, RMDD, Namchir

Govina Sharma, Revenue Surveyer, LR & DM Department

Bishnu Prasad Sharma, Assistant Engineer, RMDD, Namchi

> Karishma Rai Forest Guard

Forest and wildlife Department

D.K. Rai Block Officer (1) Tem: Tarkti, South Sikkim Block Officer,

Forest Env & WL Management Department