


JOINT INSPECTION CERTIFICATE

In a Joint inspection for the forest land comprising of Khasra No. 1175 measuring 00-30-00 hect in Mohal Naddi in Tehsil Dharamshala , District Kangra (H.P) held on 04-09-2020 by the following officers .

1. Executive Engineer, Jal Shakti Division , Dharamshala
2. Sub- Divisional Magistrate , Dharamshala .
3. Divisional Forest Officer, Dharamshala

Alternative sites were examined during the inspection. The forest land involved in the finally accepted alignment is minimum and unavoidable because there is none of Govt. Non – forest land which could be used for this purpose . There is no objection if the forest land coming in the alignment of project is diverted to Jal Shakti Vibhag Dharamshala for the construction of sewage treatment units at Naddi , Tehsil Dharamshala Distt Kangra (H.P)


Executive Engineer
Dharamshala


Sub- Divisional Magistrate
Dharamshala


Divisional Forest Officer
Dharamshala