

॥ कार्यालय प्रभागीय वनाधिकारी, बद्रीनाथ वन प्रभाग, गोपेश्वर ॥

Email-dfo_badrinath_uta@yahoo.co.in

Phone no-01372-252175

पत्रांक 257/12-1, गोपेश्वर, दिनांक जुलाई 18 / 2020।
सेवा में,

अपर प्रमुख वन संरक्षक एवं नोडल अधिकारी,
वन संरक्षण, फॉरेस्ट कॉलानी, इन्दिरानगर, देहरादून।
द्वारा:- वन संरक्षक,
गढ़वाल वृत्त, उत्तराखण्ड, पौड़ी।

विषय:- ऑनलाईन प्रस्ताव नं०- FP/UK/Road/38079/2019 जनपद चमोली में पी०एम०जी०एस०वाई० के अन्तर्गत धुर्मा-कुण्डी मोटर मार्ग के किमी० 02 में मोखमल्ला तक मोटर मार्ग का निर्माण हेतु 3.275 है० वन भूमि का हस्तान्तरण।

संदर्भ:- भारत सरकार पर्यावरण एवं जलवायु मंत्रालय देहरादून का पत्रांक 08बी/यू०सी०पी०/०६/ 111/2019/एफ०सी०/1212 दिनांक 03.09.2019

महोदय,

उपरोक्त विषयक संदर्भित पत्र के क्रम में उपप्रबन्धक, एन०पी०सी०सी०, कैम्प कार्यालय देवटोली, कर्णप्रयाग 246444 कर्णप्रयाग ने अपने पत्र सं० एन०पी०सी०सी०/पी०एम०जी०एस०वाई० दिनांक 15.07.2020 से आपत्ति का निराकरण कर सूचना निम्नानुसार इस कार्यालय को प्रेषित की गयी है:-

| | | |
|----|---|---|
| 1 | It is Seem that the proposal is for diversion of 3.275 ha. and rest of muck dumping but in many documents area of forest land submitted for diversion is mentioned as 2.7ha. | The document is uploaded after making suitable correction. |
| 2 | Land Schedule Submitted is not counter signed by DFO | Land schedule is uploaded after getting counter signed by DFO. |
| 3 | Area mentioned in CA Scheme is 5.40ha instead of 6.55ha. | The document is uploaded after making suitable correction. |
| 4 | CA site name and area is not mentioned in CA suitability certificate . | The document is uploaded after making suitable correction. |
| 5. | As per tree enumeration list 190 trees are of banj out of 223. State govt. may explore some other alignment to reduce the number of trees. It is also not mentioned whether the tree culcation is done on 7m. to 9m and what is the actual number of trees to be cut futher, the number of tree in 0-10 dia class is not submitted. | A joint visit of the site was done with forest department on dated 21.01.2020. were is was observed that the tree, to be cut is minimum in the above porposed alignment of the motor road. Joint Site Visit report is attached. the tree culcation is done in 7m. and the actual of tree to be cut is 223nos. out of 190nos are banj trees. there is no any tree in 0-10 dia class. relevant documents are uploaded after making suitble correction. |
| 6. | Name of CA area mentioned online is kundi but in CA scheme and CA site suitability is in mokha malla . | The document is uploaded after making suitable correction. |
| 7. | Comments of DFO are incomplete against para 6 in part II. State Govt. may provide comments of DFO agaist 'brief note on vulnerability of the forest area to erosion.' i.e. para 6 Part II. | comment has been made by dfo in para 6. |
| 8. | State govt. may submit original copy of the revised documents in view of above points. | The hard copy of above points are submitted in original. |

अतः उपरोक्त प्रकरण में अपने स्तर यथोचित कार्यवाही करने की कृपा करे।

संलग्न:- यथोपरि।

भवदीय,

(आशुतोष सिंह)

प्रभागीय वनाधिकारी,
बद्रीनाथ वन प्रभाग, गोपेश्वर।

पत्रांक:- 257 / 12-1 दिनांकित।

प्रतिलिपि:- वन संरक्षक, गढ़वाल वृत्त, उत्तराखण्ड पौड़ी को सूचना एवं आवश्यक कार्यवाही हेतु प्रेषित।

प्रतिलिपि:- उपप्रबन्धक, एन०पी०सी०सी०, कैम्प कार्यालय देवटोली, कर्णप्रयाग 246444 को उपरोक्तानुसार सूचना प्रेषित।

(आशुतोष सिंह)

प्रभागीय वनाधिकारी,
बद्रीनाथ वन प्रभाग, गोपेश्वर।