JUSTIFICATION OF SELECTING THE ROUTE AFTER EXAMINING ALL THE ALTERNATIVES

60	80	07	90	05	04	03	02	01	No SI.
Suitability from O&M	Right of Way resistance	Rich Crop in the Corridor	Wildlife Sanctuary	Number of trees actually to be felled out of enumerated trees (considering hills)	Forest involvement & tree involvement in Forest	Vicinity to Towns	Stability of the Area	Approach Road & Accessibility	Criteria
Most suitable	Less	Less	Nil	No. of Trees: 265 nos.(Incl. Poles)	Minimum Forest Land- 10.046 Ha	Passing by the side of the Rabong villiage.	Stable	Approx. 0.5 kms walking needed to reach line	Alternative-I
Suitable	Comparatively more	Moderate	Nil	No. of Trees - 410 nos.	More than Alt-I Forest Land- 12 Ha approx.	Passing by the side of the Rabong & Chaten	Less Stable	Approx. 1 kms walking needed to reach line	Alternative-I Alternative-II
Less Suitable	More than Alt-I& Alt-II	More	Nil	No. of Trees- 450 nos.	More than Alt-I& Alt-II Forest land- 14 approx. Ha.	Passing by the side of the Ranangchu & Chaten	2/3 hill slide zones found	Approx. 1.25 kms walking needed to reach line	Alternative-III

Chief Engineer Power Department Government of Sikkim Ganglok