

Joint Inspection Report


Joint inspection report for the construction of Solid Waste Management Project near HRTC workshop by Urban Development Department, HP was conducted on spot on 20.12.2019 by the Committee comprising of SDO (Civil), Dharamshala, Divisional Forest Officer, Dharamshala, Executive Environment Engineer, Dari and Additional Commissioner, Dharamshala Municipal Corporation.


Detail of land in respect of location is as under :-


1. Solid Waste Management Project near HRTC workshop (under Smart City Mission).

Owner of Land	Mohal	Khasra No.	Khata No.	Kisam of Land
Govt. of HP	Up Mohal	1898/1	<u>445 min</u>	Jangal Mehfuja
Forest Department	Dharamshala	1898/2	416 min	Gair Mehduda
		1900/1		

The Joint Inspection Committee inspected all the alternatives with a view to avoid/ minimise the use of forest land and the Joint Inspection Committee have come to conclusion that the land of above location and Khasra Nos of forest land is the minimum requirement of the proposed Solid Waste Management Project near HRTC workshop and is absolutely essential.


SDO (Civil),
Dharamshala


DFO,
Dharamshala
Divisional Forest Officer,
Dharamshala Forest Div.
DHARAMSHALA


AEE, PC6
XEN Environment
Dari, Dharamshala


Additional Commissioner
Dharamshala Municipal Corporation