


SITE INSPECTION REPORT

Certified that, the undersigned has inspected the site on 07-09-2019 and site inspection report is as under.

The proposed area 0.54 Ha. is located in Alagilawada RF of Alagilawada village Sy.No. 263, Kadathi Village of Sy.No. 381, Telagi village of Sy.No. 202 of Harapanahalli Taluk. This area is inevitable for user agency for laying of pipeline to fill 60 Tanks of Harapanahalli Taluk for drinking water purpose. There is not much vegetation in the area. The area is open blank and the proposed work will not cause much disturbances to the Flora and Fauna in the proposed area.

Date : 13-09-2019
Place : Davanagere


Deputy Conservator of Forests,
Davanagere Division, Davanagere