

## JOINT INSPECTION REPORT

Today on 10-06-2022 we the following officers jointly inspected the survey line of Construction of 60 mtr span Steel Girder Motorable Bridge including approaches at Chakli Bagla under NABARD for a length of 1.0 km Passing through Co. 99/N of Nowshera Range, Nowshera forest Division and found this is the only survey line where minimum forest land and forest crop is involved and there is no other alternative other than this survey line for connectivity of this village.

Detail of area involved is as under:-

Total length of road	RD	Total length passing through Forest	Width to be required
1.0 Km	0/0 to 0/775	772.00 mtr	6.00 mtr


Width of the road= 6.0 mtr

Total area under road construction= 0.60 Ha

Total forest area under road construction= 0.463 Ha

Dumping sites identified in the forest area= Nil


Total area under dumping sites= Nil

  
JE

PWD(R&B) Division Rajouri

  
AEE

PWD(R&B) Division Rajouri



Block officer  
Androoth

  
Range Officer  
Nowshera