

FORMATE FOR JOINT INSPECTION REPORT FOR FOREST CONSERVATION ACT 1980 CLEARANCE

SL No.	Particular	Report																
1	Name of Project	Rehabilitation of Flash Flood Victims of Tsong Village at Dubdi, Yuksom in West Sikkim																
2	Brief of Joint Report	The User Agency LR&DM Department, West District Has proposed for Rehabilitation of Flash Flood of Tsong Village at Dubdi, Yuk West Sikkim. The proposed area falls under Khasmal land.																
3	Date of Joint Inspection																	
4	Date of Land (in Ha)	4 th March 2020																
5	Participant:	<table> <tr> <td>a. Name</td> <td>Plot No.</td> <td>Area</td> <td>Status of Land</td> </tr> <tr> <td>b. Designation</td> <td>2/P& 12/P</td> <td>8 Ha</td> <td>Khasmal</td> </tr> <tr> <td>c. Department</td> <td>P.R Limboo B.O.T. Yuksom</td> <td>Land Revenue Department</td> <td>i. Bimal Gurung R.I</td> </tr> <tr> <td></td> <td>II. R.P Sharma Surveyor, S&D II. Yanchen D Bhutia. R.S</td> <td></td> <td>III. Mamita Gurung FG</td> </tr> </table>	a. Name	Plot No.	Area	Status of Land	b. Designation	2/P& 12/P	8 Ha	Khasmal	c. Department	P.R Limboo B.O.T. Yuksom	Land Revenue Department	i. Bimal Gurung R.I		II. R.P Sharma Surveyor, S&D II. Yanchen D Bhutia. R.S		III. Mamita Gurung FG
a. Name	Plot No.	Area	Status of Land															
b. Designation	2/P& 12/P	8 Ha	Khasmal															
c. Department	P.R Limboo B.O.T. Yuksom	Land Revenue Department	i. Bimal Gurung R.I															
	II. R.P Sharma Surveyor, S&D II. Yanchen D Bhutia. R.S		III. Mamita Gurung FG															
6	Enumeration List of Forest Crop and GPS coordinates:	<ul style="list-style-type: none"> i. Enumeration list enclosed ii. GPS coordinates enclosed 																
7	Legal status of Forest Land	<table> <tr> <td>a. Gorucharan</td> <td rowspan="3">Khashmal</td> </tr> <tr> <td>b. Khasmal</td> </tr> <tr> <td>c. Reserve Forest</td> </tr> <tr> <td>d. Any other</td> <td></td> </tr> </table>	a. Gorucharan	Khashmal	b. Khasmal	c. Reserve Forest	d. Any other											
a. Gorucharan	Khashmal																	
b. Khasmal																		
c. Reserve Forest																		
d. Any other																		
8	Legal status of pvt. Land as per 1951-52 record (Details of pvt. Land to be attested and attested copy Cadastral Map)	Yes																
9	Item- wise breakup of Forest Land required as per project																	
10	Whether any National Park, W/L Sanctuary involved or not	No																
11	Types of Vegetation: <ul style="list-style-type: none"> a. Top Canopy b. Middle Canopy c. Ground Canopy 	Top, Middle and Ground Canopy																

12. Density of Crop (in %)	Above 40%
13. No. of felling of trees, poles and other forest produce involve or not	Yes (enumeration list enclosed)
14. Brief observation of inspection team	The Joint Inspection was done along Land Revenue Department, Panchayat members of affected village & Local public. The area proposed for rehabilitation was found stable and falls under Government Khasmal.
15. Sketch map of proposed project area showing detail alignment	Copy Enclosed.


Forest Department


P. R. Limboo
Divisional Forest Officer

West Territorial Division
FEWMD, Govt. of Sikkim

iii.

Land Revenue Department
Sub-Divisional Magistrate


Yuksum, West Sikkim

ii.


Sub-Divisional Magistrate
Yuksum, West Sikkim

iii.


Mamita Gurung
Forest Guard (T)
Yuksom Range


P. R. Limboo
BLOCK OFFICER
YUKSAM (T)