


Joint VERIFICATION

On dated 23-07-2021, we the officials of PWD (R&B) department, Const. Div. III, Jammu, Sub-Div. Achnoor-I and Forest department, Range office Thakrakote, B.O. Talwara. The joint verification of road namely Kattar to Bal Saroh (Kund Kanyasi) under NABARD RD 1200 to RD 2675 from Km 1st to Km 3rd has been completed, whereas Km 1st to Km 3rd is found alignment under Range office Thakrakote, B.O. Talwara, Reasi.

S.No.	Name of official	Designation.	Signature
①	Harrinder Singh Selli	T.E	23/7/21
②	Rajesh Gupta	B.O. Talwara	
③	Brij Mohan	B.O. Talwara	
④	Mohinder Kumar	Dly. wager (PWD)	
⑤	Deep Kumar	Dly. wager (PWD)	DEEP KUMAR

OFFICE OF THE EXECUTIVE ENGINEER PWD (R&B) CONST. DIV. NO.III

JAMMU.

The Divisional Forest Officer,
Reasi.

No.: - 7754-55
Dt.: - 31-07-2021


Sub.: - Joint verification of Kathar to Bal Saroh (Kund Kanyari) Km.1st to Km.3rd under NABARD.

Sir,

In reference to above cited subject that the joint verification of the above noted road was conducted on 23-07-2021 along with field staff of your Department (copy enclosed).

In this regard you are requested to give the detail of land area coming under the alignment of said road (including number of trees / plants) and also requested to submit the KMZ file for uploading the proposal for transfer of land on PAVESH Portal for early completion of work.

Yours faithfully,


Executive Engineer
PWD(R&B) Const. Div No.III
Jammu

Copy to the:-

1. Assistant Executive Engineer PWD(R&B) Sub-Division Akhnoor-I for information and follow up.