

JOINT INSPECTION REPORT

Serial No.	Particulars	Details
1	Name of project	New link road from Andheri Bridge to Upper Samdur Village
2	A brief of project	Upper Samdur village which is located above NH10, is devoid of any vehicular connectivity presently. They are using army road located within the defence area from the upper reaches from which village is connected with series of CC footpath, bridle path etc. At present army has started fencing of their compound which is adversely affected their movement take off point of the proposed road falls under forest department the total land involved for "Construction of link road from Andheri Bridge ,NH10 to upper Samdur under Namcheybong Constituency km 0.00 to 2.00 in east Sikkim" about 3.2 Ha, out of which 0.1502 Ha falls in reserve forest Khasmal
3	Date of joint inspection	10/01/2019
4	Participants <ol style="list-style-type: none"> 1. Name 2. Designation 3. Department 	1. Sonam .W. Lepcha, BO, Survey & Demarcation 2. Gyurmed Choden Lepcha ,BO (Ranipool)(T) Range 3. Dharani Dhar Sharma, Survey Inspector, LR&DMD, GANGTOK 4. Sushan T Rai, Revenue Surveyor, LR&DMD, GANGTOK 5. Sonam Gyalsten ,Junior Engineer, R&B, GANGTOK
5	Details of land in hectares <ol style="list-style-type: none"> 1. Private land 2. Forest land (Khasmal) 3. Total forest land involved 	3.0498Ha 0.1502Ha 0.1502Ha
6	Legal status of forest land <ol style="list-style-type: none"> 1. Gaucharan 2. Khasmal 3. Reserved forest 4. Road reserve 5. Any other 	0.00Ha 0.1502Ha 0.00 Ha 0.00Ha 0.00Ha
7	Legal status of private land as per 1951 to 1952 records (details of private land to be attested and attested copy of Cadastral map)	NA
8	Item wise breakup of forest land required as per project	1. Gaucharan 0.00Ha 2. Khasmal 0.1502Ha 3. Reserved forest 0.00 Ha
9	Whether any National Park \wild life sanctuary involved or not	NO
10	Types of vegetation <ol style="list-style-type: none"> 1. Top canopy 	Open forest area with Ground Flora

JOINT INSPECTION REPORT

	2. Middle canopy 3. Ground flora	
11	Category of density	Open
12	No. of falling of trees/poles and forest produces involved or not, if yes indicated details of plot etc.	NO
13	Topography of project area, soil type of forest area.	
14	Brief observation of inspection team	During survey it has been found that connectivity to Samdur from NH 10 is essential to improve the living standard of the people of that area.
15	Sketch map of propose project area showing details alignment	Details Included
16	Enumerations list of trees/poles/shrubs/and medical herbs etc.	N/A
17	Any others aspects related to project in forest area	N/A
18	Certificate of DFO (T) concerned if trees falling is not involved.	Details Included

Representatives of:

Block Officer

Survey & Demarcation

Sonam W. Lepcha
Sonam W. Lepcha
 Block Officer.....
 Survey & Demarcation Division
 Forest Env. Wildlife Mngt. Deptt.

Block Officer

Ranipool (T) Range

[Signature]
Block Officer
 Ranipool (T) Block.....
 FEWMD

Surveyor Inspector

LR&DMD, Gangtok

[Signature]
SURVEY INSPECTOR
 District Collectorate, East
 Gangtok

JOINT INSPECTION REPORT

Revenue Surveyor

LR&DMD, Gangtok

Junior Engineer

(R&B), Gangtok

REVENUE SURVEYOR

District Collectorate
East District, Gt. Sikkim

Junior Engineer

Sub-Division No. IV

Roads & Bridges Deptt.

Govt. of Sikkim, Gangtok