

Note Sheet

The disposal of solid waste management in the State, to some extent has been quite critical due to unavailability of appropriate dumping grounds. This problem has further accentuated with the latest development at the Marchak Dumping Ground.

As such, after detailed deliberations with the officials of UDHD/Forests/GMC, a joint inspection was conducted, whereby a land covering an area of 3.44 acres has been identified at Bhasmey Reshi below Chameray Bhir along the Rangpo - Rorathang Road. This appears to be forest land.

PCCF cum Secretary, Forests may kindly examine and put up a detailed proposal as acquisition of this land is of immediate concern. Secretary, LRDM may kindly see enroute.

Secretary, LRDM
PCCF cum Secretary, Forests

(Ringnen Ongmu)
Chief Secretary

13/9/14

15/9/14

CFC(T)

For joint inspection by field staff.

CFC

For m. action for immediate joint inspection.

15/9/14

DFO (T)/Ensh

15/9/14

For urgent for m. action on above.

15/9/14

1.39 ha