



SITE INSPECTION REPORT

1. Name of the proposal : Construction of Nagloli Storage Tank
Scheme Tal Shrivardhan Dist. Raigad.
2. Forest Area involved : 6.5000 Ha
3. Location : Village Nagloli Tal. Shrivardhan
- Division : Roha Forest Division
- Range : Shrivardhan.
- Round : Borli Panchtan
- Beat : Borli
- Compartment No. : As per list attached.
- Coupe No. : -- "--
- Forest S. No. : -- "--
4. Date of site inspection : 23 / 12 / 2014
5. Details of Forest Type and flora and existing crop with botanical names of species : Mixed deciduous Forest Area with normal growth of trees. *Terminalia tomentosa*, *Bridelia retusa*, *Tectona grandis*, *Acacia*, *Kinjal* etc.
6. Details of fauna including their Population and distribution game sanctuary, National Park of Reserve : -----
7. Other aspects of importance : No
- (a) Historical/archeological : Nil
- (b) Geographical : Nil
- (c) Religious : Nil
- (d) Geological : Nil
8. Remark regarding sensitivity of area likely to be affected due to project : Not Sensitive
9. No. of Photographs (If enclosed) : Nil
10. Whether any work is violation of the Act has been notice. : No Violation is noticed


Asst. Conservator of Forests
(F.L.C.S.), Roha.


V.B. Suryavanshi
Deputy Conservator of Forests,
Roha Forest Division, Roha.