

## ଅନୁଷ୍ଠାନିକ - 12

### Check list for site inspection by the DFO/CF/CCF:

At present the site Inspection Report submitted by the DCF level is very sketchy and does not convey much to higher officers going for verification of the facts in the field monitoring of project on a later date as mandated in the guidelines. This is possible only when exhaustive check is carried out at the DCF/DFO level. This would help the higher authorities to verify the facts to arrive at appropriate decisions.

S.n.	Particular	Inspection Report By CCF/ DFO (T)
1	Extent is hectares.	2.070 ha.
2	Location (Lat-long) of the forest land proposed for diversion.	Attached
3	Legal status of the forest land (Protected forest, reserved forest, revenue forest lands or any other forest land)	RF & PF
4	Demarcation of the area with temporary claims etc.	Yes
5	Any signs of encroachment.	No
6	Any activity already taken up within the forest land or adjoining non-forest land as part of the proposed project by the user agency. Details of action taken against the User Agency in case of violation of the FC Act and guidelines there under.	No
7	Status of vegetation. Site quality, species composition etc.	IV-A, IV-B
8	Importance of area from wildlife point of view. Status of wildlife (density and abundance of important species, bird life, reptiles, butterflies and other scheduled animals, any endangered wildlife). Any latest census of wildlife in this area.	None
9	Endemism of flora/fauna or any other unique ecosystem in the area.	None
10	Current land use. Is this area managed as per prescriptions in the working plan and, if not, why?	None
11	Importance of the area from historical or religious point of view.	None
12	Any dependent persons/families on this land.	No
13	Any displacement of persons proposed.	No
14	Is there any Rehabilitation and Resettlement Plan for the persons to be affected? Is there any dissenting voice among the persons proposed to be displaced?	No

15	Compensatory afforestation proposed is on forest land or non-forest land. Location of this area, suitability of the area for CA. If in the degraded forest land then what is the current working plan prescription for the area ? Distance of the non-forest land for CA from the nearest forest area. number of patches in case the area should be more than to kms.	Double Degraded Forest Land 4.140 ha.
16	Proposed area should not be part of any protected area. Also distance from the boundary of the nearest protected area should be more than 10 kms.	No
17	Dependence of tribals in the area. Whether the rights of the tribals have been recognized in this area.	No
18	Utility of the project, including the people living in close vicinity of the project.	To Provide Power Supply in Rural Area
19	In case of renewal whether all the conditions stipulated in the earlier sanction order have been complied with.	No
20	Alternatives examined by the user agency in case of non-site specific projects.	Yes
21	A certificate by the user agency that the forest land requested for diversion for non-forestry purpose is bare minimum.	Yes
22	Any scope of saving tree growth while ensuring that the purpose for which the forest land is being diverted is also not adversely affected.	No
23	Any other issue of significance.	No
24	Specific recommendations of the DFO with reason for approval of the project.	Yes

Divisional Forest Officer  
कर्म मंत्रालय कार्यालय  
दृष्टिगत वर्ष मण्डल, सागर

Place-Sagar

# कार्यालय उपवन मण्डल अधिकारी देवरी, सागर

9424793834, Email- [sdodeori@mpforest.org](mailto:sdodeori@mpforest.org)

क्रमांक/एसडीसी/2015/ 366

देवरी दिनांक 25/03/2015

प्रति,

श्रीमान वन मण्डल अधिकारी ✓

दक्षिण वन मण्डल सागर

**जन वन विवरण-** सागर जिले के अंतर्गत गौरज्ञामर से देवरी 33 के व्ही. विद्युत लाइन डालने हेतु प्रभावित 2.070 हे. वन भूमि आवेदक संस्थान को उपयोग पर देने वाला।

**संदर्भ:-** आपका पत्र क्रमांक 1116 सागर दिनांक 20.03.2015।

उपरोक्त विषयांतर्गत एवं संदर्भ में निवेदन है कि आपके संदर्भित पत्र के परिपालन में निर्देशानुसार मेरे द्वारा मौका स्थल का संयुक्त रूप से स्टॉप के साथ घूमफिर कर निरीक्षण किया गया। निरीक्षण के दौरान श्री निखिल गुप्ता सहायक अभियंता सागर द्वारा गौरज्ञामर से देवरी 33 के व्ही. विद्युत लाइन निकालने के लिए पोल खड़े करने के स्थल बताए गए। जिनकी मौका स्थलों की जी.पी.एस. रीडिंग ली गई एवं पंचनामा तैयार किया गया। जो उक्त 33 के व्ही. विद्युत लाइन निकालने के लिए पोल खड़े करने के स्थल बताए गए, जिनकी मौका स्थलों की जी.पी.एस. रीडिंग ली गई एवं ली गई जी.पी.एस. रीडिंग को गूगल अर्थ में प्लाटिंग की गई जिसके अनुसार बीट चीमाडाना व गोपालपुरा के कक्ष क्र. 967, 968 व 956 में जी.पी.एस. रीडिंग बिन्दू क्र. 01 से 13 तक एवं आगे भी स्थल नीमधाटी में एन.एच. 26 निर्माण के दौरान पहाड़ी क्षेत्र की बहुत अधिक खुदाई (कटिंग) व भराई (फिलिंग) होने के कारण रोड किनारे के पास से 33 के व्ही. विद्युत लाइन निकालने के लिए पोल खड़े करने का स्थान उपलब्ध नहीं है। जिस कारण रोड किनारे से लगभग 100 से 150 मीटर के अन्दर वन क्षेत्र से निकालने का स्थान श्री निखिल गुप्ता सहायक अभियंता सागर द्वारा बताया गया। जिसमें सागौन एवं अन्य प्रजाति के बड़े एवं छोटे वृक्ष आने की संभावना है। जिस संबंध में श्री निखिल गुप्ता सहायक अभियंता सागर ने बताया कि 33 के व्ही. विद्युत लाइन को सीधा नहीं निकालकर (खीचकर) सभी प्रकार के बड़े व छोटे वृक्षों को बचाकर 33 के व्ही. विद्युत लाइन को घूमाकर (Angle) में लेकर या U (Shape) आकार दिया जाकर निकालने (खीचने) को कहा गया है। जबकि मेरे विचार अनुसार उक्त विद्युत लाइन के लिए 09 से 13 मीटर ऊँचाई तथा कम से कम 05 से 07 मीटर ऊँडाई तक आवश्यक रूप से साफ (Clear) होना चाहिए जिससे कि किसी प्रकार का खतरा होने की संभावना नहीं रहें। वैसे भी विद्युत लाइन के नीचे वर्ष में दो बार छः छः माह के अन्तर से सफाई का कार्य किया जाता है। जिसमें भी पोल क्रॉप एवं अग्रिम पौध की भी सफाई कार्य के तहत कटाई किया जाना संभव होगा। जॉच प्रतिवेदन आपकी ओर उचित एवं आवश्यक कार्यवाही हेतु सादर संप्रेषित है।

**सलग- प्रथमा।, 4.P.S. Reading, plotting.**

वन मण्डल फाइल

उपवन मण्डल अधिकारी

देवरी (सामान्य)

देवरी दिनांक /03/2015

पृष्ठ क्रमांक/एसडीसी/2015/

प्रतिलिपि:-1) श्रीमान गुरुव्य वन संरक्षक सागर वन वृत्त की ओर सादर सूचनार्थ संप्रेषित हैं।

2) अधीक्षक अभियंता, म.प्र.पू.क्षे.वि.वि.क. लिमि. सागर की ओर सूचनार्थ संप्रेषित हैं।

3) वन परिक्षेत्र अधिकारी गौरज्ञामर को सूचनार्थ एवं आवश्यक कार्यवाही हेतु अग्रेषित कर लेख है कि आप प्रभावित वन भूमि 2.070 हे. का वैकल्पिक वृक्षारोपण योजना तैयार कर शीघ्र प्रस्तुत करें।

उपवन मण्डल अधिकारी

देवरी (सामान्य)

1295

30/3/15

## मौरजामर से देवरी 33 के.व्ही. विधुत लाइन एन.एच. 26 जी.पी.एस. रीडिंग

क्र.	अ.	दे.	क्र.	अ.	दे.
1	23 29 29.7	78 58 09.0	2	23 29 28.6	78 58 11.1
3	23 29 27.7	78 58 12.6	4	23 29 26.0	78 58 14.7
5	23 29 24.5	78 58 16.3	6	23 29 20.8	78 58 17.4
7	23 29 19.5	78 58 19.5	8	23 29 16.7	78 58 19.7
9	23 29 13.1	78 58 20.1	10	23 29 11.9	78 58 19.5
11	23 29 09.7	78 58 19.6	12	23 29 08.0	78 58 20.1
13	23 29 05.7	78 58 20.4	14	23 29 03.3	78 58 20.1
15	23 29 01.1	78 58 20.5	16	23 28 57.7	78 58 20.9
17	23 28 54.7	78 58 21.4	18	23 28 51.9	78 58 21.9
19	23 28 48.2	78 58 22.4	20	23 28 45.4	78 58 23.1
21	23 28 42.6	78 58 23.8	22	23 28 40.2	78 58 25.0
23	23 28 36.9	78 58 26.9	24	23 28 32.2	78 58 39.6
25	23 28 27.8	78 58 31.6	26	23 28 25.0	78 58 32.9
27	23 28 19.6	78 58 35.3	28	23 28 15.3	78 58 37.5
29	23 28 11.3	78 58 39.6	30	23 28 08.4	78 58 41.1
31	23 27 56.5	78 58 46.9	32	23 27 52.2	78 58 48.9
33	23 27 50.6	78 58 50.0			

श्री के.आर. जाधव  
उपवन भंडल अधिकारी

देवरी (सामान्य)

देवरी दिनांक /03/2015

पृष्ठ-क्रमांक/एसडीसी/2015/