

SITE INSPECTION REPORT


Certified that the undersigned has inspected the proposed site on 08-06-2017 and site inspection report is as under.

The proposed area 0.17 Ha. is located in Ramapura Sy. No. 13 (0.034 Ha.), Konammanahalli Sy. No. 1 (0.110 Ha.), and Palakanahalli Sy. No. 46 (0.029 Ha.) Davanagere Taluk, Davanagere District. This area is inevitable for user agency for laying of drinking water supply pipeline from Ramapura village to Halagavadi village. Which area to be located at elevated places for water supply scheme. There is not much vegetation in the area. The area is open and blank. There will not be much disturbances to the flora and fauna in the proposed area.

It is further certified that the land is free from any encroachments as well as any encumbrances and no violation of provisions of FC Act-1980.

Date : 08-06-2017

Place: Davanagere.


Deputy Conservator of Forest,
Davanagere Division, Davanagere.