

SITE INSPECTION REPORT

1	Name of the Project	Upper Lanth Irrigation Project
2	Name of the District/Division	Bolangir Forest Division/Bolangir
3	Date of inspection	23.08.2017
4	Name and designation of inspecting officer	Sri Rashmi Ranjan Nayak, Divisional Forest Officer, Bolangir Forest Division
5	Name and designation of Forest Officers who attended the inspection including the representative of the user agency	Sri Nalinikanta Jayasingh, A.C.F. Sri Raj Kishor Harpal, R.O. Lathor Sri Dinabandhu Meher, R.O. Harishankar Sri Manoranjan Mahapatra, Executive Engineer, Padampur Investigation Division, Padampur Sri Tankadhara Majhi, Asst. Engineer, Padampur Investigation Division, Padampur
6	Legal status of forest land with area proposed for diversion.	Bender I RF
7	If area required for diversion has been demarcated on the ground.	Yes
8	Condition of vegetation and type of forest land in applied area.	List enclosed in a separate sheet. The species available in the applied area are Sal, Bija, Asan, Kendu, Arjun, Dhura, Mahul, Jamu, Char, Moi, Salai etc.
9	No. of trees to be felled and its impact in the eco-system.	No trees felled till date.
10	Whether any rare /endangered/unique species of flora and fauna found in the area – if so details thereof.	Not Found
11	Whether any protected archaeological/ heritage site/ defense establishment or any other important monument is located in the area. If so, the details thereof with NOC from competent authority, if required.	-
12	Whether the requirement of forest land as proposed in D.P.by the user agency is unavoidable and barest minimum for the project. If no, recommend area item-wise with details of alternatives examined	During site inspection it is observed that, the forest land diverted is unavoidable and barest minimum requirement of the project.
13	Whether any work in violation of the act has been carried out (yes/No) is Yes details of the same including period of work done, action taken on erring officials. Whether work is violation is still in progress	No violation till date
14	Details of site inspected	Inspected on dtd. 23.08.2017. The boundary of forest land proposed to be diverted has been demarcated on the ground by erecting 4' ft high reinforced RCC Pillars inscribed with its Sl. No with DGPS Coordinates which was approved by ORSAC, Bhubaneswar, Odisha. The distance between two pillars kept within 50 mtrs (Visible Distance). The pillars are clearly visible from pillar on both side.

Divisional Forest Officer,
Bolangir Forest Division

21.8.2017
Divisional Forest Officer
Bolangir Forest Division
Bolangir