

## **3D Subsidence Analysis Report**

Within the Duarmara Block three exploratory well were drilled by Oil India Limited, Duarmara-1 (1970), Duarmara-2 (1985) and Duarmara-3 (1986). During the drilling of these wells no surface subsidence has been observed within the block area. The proposed drilling and work-over activities mainly for small holes to ascertain the commerciality of the hydrocarbon prospectively within the block area. Hence, there is no possibility whatever it may be for any subsidence due to the exploration activities carried out afresh in this block. Further, oil and gas production involves extraction of the pressurised fluids (oil/gas) from the subsurface reservoir sands which in case of Duarmara Block generally lies 3000-5000m below the ground level; therefore not affecting the surface rock integrity.

Keeping in mind above, 3D Subsidence Analysis Report is not essentially required at present for the Duarmara Block.

For Oilmax Energy Private Limited,

Dr. Rabi Bastia

CEO – Oil and Gas

CIN: U40101MH2008PTC185357
3-A, Omkar Esquare, Chunnabhatti Signal,
Eastern Express Highway, Sion (East), Mumbai - 400 022

Tel.: +91 22 4244 1100 Fax: +91 22 4244 1111

Web: www.oilmax.in