1. In 4-(ii) Density shown is of 2 patches, whereas area involved is only 0.2107 ha.
2. Eco- class is III not I
3. In 5-It is showing No Data justify it.
4. In 7- show the distance from nearest forest area. No Data is not acceptable.
5. In 13- (ii) Give details of area identified for C.A. In hard copy it is some forest block and here it is the NH-91 Roadside. Hard copy showing modinagar range also rectify this anomaly.