

1. The Google Earth screenshot is not matching with the layout plan of the project uploaded.
2. Component-wise break-up in SNo B-2.4 of Form A, Part-I, has been incorrectly filled.
3. It is not clear how in 7 m width of RoW of the line passing through dense wooded patches, no tree felling is proposed.