

1- On observing the KML file the proposed alignment is passed through a river but no bridge component is shown in the component wise break up- Kindly clarify.





- 2- Certificate of MOU uploaded for the CA area is not correct. Kindly upload the correct MOU certificate.
- 3- In CF recommendation, Part III is not uploaded, some other document is uploaded. Kindly upload the Part III.
- 4- As the proposal involved the felling of the Ban trees, Upload the annexure 22 with the sign and comment of Forest Conservator or make comment in the recommendation regarding the banj tree.

.....NODAL OFFICE.....